THOMAS PAINE ELEMENTARY SCHOOL

51,866 SF 1968, 1995, 2000				
			Unit	Cost
<u>Site</u>	Qty		Cost	Estimate
Additional Site Improvements - ADA Compliance, Site Drainage, Paving, Signage, etc., Playground Enhancements/Replacement and New Side Entrance Ramp/Stair(s) (District Consultant)			Lump Sum	\$700,000
25% Soft Costs (A/E Fees	, Conting	ency, C	M, Legal, etc.)	\$175,000
		Es	timated Total	\$875,000
Exterior Renovations				
Exterior Door, Hardware, Frame Replacement	11	0	\$10,000	\$110,000
Masonry Repairs - Window Lintels, Windows, Coating EIFS Repairs, Caulking, etc.			Lump Sum	\$475,000
			Subtotal	\$585,000
25% Soft Costs (A/E Fees	, Conting	ency, C	M, Legal, etc.)	\$146,250
	_	Es	timated Total	\$731,250
Interior Renovations				
Classroom Flooring - New VCT Flooring & Base and Painting	16 000	SF @	\$12	\$192,000
oldssröchn ricornig - New vor ricornig a Base and ranking	10,000			Ψ152,000
Corridor Ceiling Replacement and Painting Walls		SF @	\$20	\$155,000
			•	
Corridor Ceiling Replacement and Painting Walls	7,750	SF @	\$20	\$155,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware	7,750 99	SF @ @	\$20 \$4,000	\$155,000 \$396,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance	7,750 99 4	SF @ @ @	\$20 \$4,000 \$125,000	\$155,000 \$396,000 \$500,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance	7,750 99 4	SF @ @ @	\$20 \$4,000 \$125,000 \$50,000	\$155,000 \$396,000 \$500,000 \$300,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator	7,750 99 4	SF @ @ @ @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator Library - Replace Finishes, Lights, etc.	7,750 99 4 6 51,866	SF @ @ @ @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum Lump Sum	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000 \$175,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator Library - Replace Finishes, Lights, etc. New ADA Compliant Interior Signage	7,750 99 4 6 51,866	SF @ @ @ @ SF @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum Lump Sum \$1	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000 \$175,000 \$51,866
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator Library - Replace Finishes, Lights, etc. New ADA Compliant Interior Signage Classroom Conversion to (6) SGI's - Finishes, Building Systems, etc.	7,750 99 4 6 51,866	SF @ @ @ @ SF @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum Lump Sum \$1 \$200	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000 \$175,000 \$51,866 \$320,000
Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator Library - Replace Finishes, Lights, etc. New ADA Compliant Interior Signage Classroom Conversion to (6) SGI's - Finishes, Building Systems, etc. All Purpose Room - Replace Finishes, New Ceilings, Expand Warmup Kitchen	7,750 99 4 6 51,866	SF @ @ @ @ SF @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum Lump Sum \$1 \$200 Lump Sum	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000 \$175,000 \$51,866 \$320,000 \$250,000
 Corridor Ceiling Replacement and Painting Walls New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware Renovate Hall Toilet Rooms - Finishes, Fixtures, ADA Compliance Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator Library - Replace Finishes, Lights, etc. New ADA Compliant Interior Signage Classroom Conversion to (6) SGI's - Finishes, Building Systems, etc. All Purpose Room - Replace Finishes, New Ceilings, Expand Warmup Kitchen 	7,750 99 4 6 51,866 1,600	SF @ @ @ SF @ SF @	\$20 \$4,000 \$125,000 \$50,000 Lump Sum Lump Sum \$1 \$200 Lump Sum Lump Sum Subtotal	\$155,000 \$396,000 \$500,000 \$300,000 \$50,000 \$175,000 \$51,866 \$320,000 \$250,000 \$200,000



67

THOMAS PAINE ELEMENTARY SCHOOL

51,866 SF 1968, 1995, 2000

			Unit	Cost
iilding Systems	Qty		Cost	Estimate
HVAC Construction				
New Unit Ventilators - Remove Existing Perimeter Units, New Unit Ventilators with New Air Conditioning (APR), New Perimeter Hot Water Radiation, Book Shelving, etc.			Lump Sum	\$1,149,000
Exhaust Fans - Replace Rooftop Units	15	0	\$2,500	\$37,500
HVAC Replacement (4) Split Systems			Lump Sum	\$56,000
Replacement of the Pneumatic Energy Management System with New DDC Electronic Controls	51,866	SF @	\$6.00	\$311,196
			Subtotal	\$1,553,696
25% Soft Costs (A/E Fees	, Conting	ency, Cl	M, Legal, etc.)	\$388,424
		Es	timated Total	\$1,942,120
Electrical Construction				
Replace PA System, Clock System and Technology			Lump Sum	\$111,623
Power/Lighting Branch/HVAC Panel Upgrades	4	0	\$25,000	\$100,000
			Subtotal	\$211,623
25% Soft Costs (A/E Fees	, Conting	ency, Cl	M, Legal, etc.)	\$52,906
		Es	timated Total	\$264,529



THOMAS PAINE ELEMENTARY SCHOOL

51,866 SF 1968, 1995, 2000


	Total Estimated	ACTUAL	Local Share
	Cost	State Share	Local Share
Site Work	\$875,000	(\$350,000)	\$525,000
Exterior Renovations	\$731,250	(\$292,500)	\$438,750
Interior Renovations	\$3,237,333	(\$1,294,933)	\$1,942,400
HVAC Construction	\$1,942,120	(\$776,848)	\$1,165,272
Electrical Construction	\$264,529	(\$105,812)	\$158,717
Total Renovations	\$7,050,232	(\$2,820,093)	\$4,230,139
		40%	60%

Renovations = Architect's estimate of eligible projects @ 40% State Aid New Construction – Eligible Square Footage x \$143/SF @ 40% State Aid



THOMAS PAINE ELEMENTARY SCHOOL

51,866 SF 1968, 1995, 2000













THOMAS PAINE ELEMENTARY SCHOOL

51,866 SF 1968, 1995, 2000









Floor plan

