

#### **WOODCREST ELEMENTARY SCHOOL**

53 185 SE 1958 1989 2000				
53,185 SF 1958, 1982, 2000			Unit	Cost
<mark>ite</mark>	Qty		Cost	<b>Estimate</b>
Additional Site Improvements - ADA Compliance, Site Drainage, Paving, Signage, etc.,				
Playground Enhancements/Replacement, Existing Front Ramp/Stairs (District Consultant)			Lump Sum	\$1,000,000
25% Soft Costs (A/E Fees	s, Conting	ency, Cl	И, Legal, etc.)_	\$250,000
		Es	timated Total	\$1,250,000
xterior Renovations				
Roof Replacement (All Sections) - Remove to Deck (Assume 10% Deck Replacement) New Insulation, Modified Roof System	53,185	SF@	\$35	\$1,861,47
Exterior Door, Hardware, Frame Replacement	13	@	\$10,000	\$130,00
Masonry Repairs - Window Lintels, Windows, Brick Pointing, Caulking, etc.			Lump Sum	\$450,00
			Subtotal	\$2,441,47
25% Soft Costs (A/E Fees	s, Conting	ency, Cl	M, Legal, etc.)_	\$610,36
		Es	timated Total	\$3,051,84
terior Renovations				
New Corridor LED Lighting and Ceiling Replacement and Painting Walls	6,640	SF@	\$25	\$166,00
Classroom Flooring - New VCT Flooring & Base and Painting	22,000	SF@	\$12	\$264,00
New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware	103	@	\$4,000	\$412,00
Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance	9	@	\$50,000	\$450,00
Teacher's Room - Replace Finishes, Sink, Cabinets, Stove and Refrigerator			Lump Sum	\$50,00
New ADA Compliant Interior Signage	53,185		\$1	\$53,18
Classroom Conversion to (2) SGI's - Finishes, Building Systems, etc.	1,600	SF@	\$200	\$320,00
Gymnasium - Demolish Stage, Replace Finishes, New Ceilings			Lump Sum	\$250,00
Library - Replace Finishes, Lights, etc.			Lump Sum	\$175,00
Hazardous Materials Abatement - VAT, Pipe Insulation, etc. (District Consultant)			Lump Sum_	\$225,00
			Subtotal	\$2,365,18
25% Soft Costs (A/E Fees	s, Conting	•	, <u> </u>	\$591,29
		Es	timated Total	\$2,956,48





#### **WOODCREST ELEMENTARY SCHOOL**

			Unit	Cost
uilding Systems	Qty		Cost	<b>Estimate</b>
HVAC Construction				
Replace Existing Boilers, Controls, Pumps, Valves, etc. in 2000 Section			\$50,000	\$100,000
New Unit Ventilators - Remove Existing Perimeter Units, New Unit Ventilators with New Air Conditioning (APR), New Perimeter Hot Water Radiation, Book Shelving, etc.			Lump Sum	\$766,000
Exhaust Fans - Replace Rooftop Units	23	@	\$2,500	\$57,500
Air Handling Units Replacement (11) in New Wing			Lump Sum	\$275,000
Replacement of the Pneumatic Energy Management System with New DDC Electronic Controls	53,185	SF@	\$6.00	\$319,110
			Subtotal	\$1,517,610
25% Soft Costs (A/E Fees	s, Conting	ency, C	CM, Legal, etc.)	\$379,403
	_	E:	stimated Total	\$1,897,013
Electrical Construction				
Replace PA System, Clock System and Technology			<b>Lump Sum</b>	\$115,580
Power/Lighting Branch/HVAC Panel Upgrades	4	@	\$25,000	\$100,000
Classroom Lighting - New LED Fixtures	18	@	\$10,000	\$180,000
			Subtotal	\$395,580
25% Soft Costs (A/E Fees	s, Conting	ency, C	CM, Legal, etc.)	\$98,895
	_	Ē:	stimated Total	\$494,475





#### WOODCREST ELEMENTARY SCHOOL

53,185 SF 1958, 1982, 2000

	Total Estimated	ACTUAL	Local Share	
	Cost	<b>State Share</b>	Local Share	
Site Work	\$1,250,000	(\$500,000)	\$750,000	
<b>Exterior Renovations</b>	\$3,051,844	(\$1,220,738)	\$1,831,106	
Interior Renovations	\$2,956,481	(\$1,182,592)	\$1,773,889	
<b>HVAC Construction</b>	\$1,897,013	(\$758,805)	\$1,138,208	
<b>Electrical Construction</b>	\$494,475	(\$197,790)	\$296,685	
Total Renovations	\$9,649,813	(\$3,859,925)	\$5,789,888	
		40%	60%	

Renovations = Architect's estimate of eligible projects @ 40% State Aid New Construction – Eligible Square Footage x \$143/SF @ 40% State Aid





#### **WOODCREST ELEMENTARY SCHOOL**










#### **WOODCREST ELEMENTARY SCHOOL**









#### WOODCREST ELEMENTARY SCHOOL

