ESTELLE V. MALBERG EARLY CHILDHOOD CENTER

e Additional Site Improvements - ADA Compliance, Site Drainage, Paving, Signage, etc., Replacement (District Consultant) 25% Soft Costs (A/E Fees, Co	ty		Unit Cost	Cost Estimate
Additional Site Improvements - ADA Compliance, Site Drainage, Paving, Signage, etc., Replacement (District Consultant)				
25% Soft Costs (A/E Fees, Co			Lump Sum	\$1,200,000
· · · · · · ·	ntinge	ency, CN	l, Legal, etc.)_	\$300,000
		Est	imated Total	\$1,500,000
terior Renovations				
Masonry Repairs - Window Lintels, Windows, Coating EIFS Repairs, Caulking, etc.			Lump Sum	\$300,000
Exterior Door Replacement	6	@	\$10,000	\$60,000
New Front Canopy - Main Entrance			Lump Sum	\$150,000
			Subtotal	\$510,000
25% Soft Costs (A/E Fees, Co	ntinge	ency, CN	l, Legal, etc.)	\$127,500
		•	imated Total	\$637,500
erior Renovations				·
Classroom Flooring - New VCT Flooring & Base and Painting 19	,000	SF @	\$12	\$228,000
New Corridor LED Lighting and Ceiling Replacement and Painting Walls 4	,714	SF@	\$25	\$117,850
New Interior Fire-Rated Doors, Frames, Closers, ADA Modifications, Intruder Hardware	76	@	\$4,000	\$304,000
Renovate Unisex Staff & Classroom Toilet Rooms - Finishes, Fixtures, ADA Compliance	8	@	\$50,000	\$400,000
Teacher's Lounge - Replace Finishes, Sink, Cabinet, Stove, Refrigerator			Lump Sum	\$50,000
New ADA Compliant Interior Signage 32	,300	SF @	\$1	\$32,300
All Purpose Room - Replace Finishes, New Ceilings, New LED Lighting, Replace Folding Door and HC Stage Lift			Lump Sum	\$250,000
Hazardous Materials Abatement - VAT, Pipe Insulation, etc. (District Consultant)			Lump Sum	\$200,000
			•	\$1,582,150
			Subtotal	ψ1,302,130
25% Soft Costs (A/E Fees, Co	ntinge	ency, CN		\$395,538



ESTELLE V. MALBERG EARLY CHILDHOOD CENTER

32,300 SF 1959, 2008

uilding Systems	Qty		Unit Cost	Cost Estimate
HVAC Construction	Qty		COSI	LStinate
New Unit Ventilators - Remove Existing Perimeter Units, New Unit Ventilators wit	h			
New Air Conditioning (APR), New Perimeter Hot Water Radiation, Book Shelving, etc.			Lump Sum	\$1,244,770
Exhaust Fans - Replace Rooftop Units	14	@	\$2,500	\$35,000
Replacement of the Pneumatic Energy Management System with New DDC Electronic Controls	32,300	SF @	\$6.00	\$193,800
			Subtotal	\$1,473,570
25% Soft Costs (A/E	Fees, Conting	ency, Cl	M, Legal, etc.)	\$368,393
		Es	timated Total	\$1,841,963
Electrical Construction				
Replace PA System, Clock System and Technology			Lump Sum	\$52,911
Power/Lighting Branch/HVAC Panel Upgrades	4	0	\$25,000	\$100,000
			Subtotal	\$152,911
25% Soft Costs (A/E	Fees, Conting	ency, Cl	M, Legal, etc.)	\$38,228
		Es	timated Total	\$191,139



ESTELLE V. MALBERG EARLY CHILDHOOD CENTER

32,300 SF 1959, 2008

	Total Estimated	ACTUAL	Local Share	
	Cost	State Share		
Site Work	\$1,500,000	(\$600,000)	\$900,000	
Exterior Renovations	\$637,500	(\$255,000)	\$382,500	
Interior Renovations	\$1,977,688	(\$791,075)	\$1,186,613	
HVAC Construction	\$1,841,963	(\$736,785)	\$1,105,178	
Electrical Construction	\$191,139	(\$76,456)	\$114,683	
Total Renovations	\$6,148,290	(\$2,459,316)	\$3,688,974	
		40%	60%	

Renovations = Architect's estimate of eligible projects @ 40% State Aid



ESTELLE V. MALBERG EARLY CHILDHOOD CENTER 32,300 SF 1959, 2008








06-08-22



ESTELLE V. MALBERG EARLY CHILDHOOD CENTER 32,300 SF 1959, 2008



| ROOF PLAN RP-1.0/SCALE: 1/32"=1'-0"



ESTELLE V. MALBERG EARLY CHILDHOOD CENTER 32,300 SF 1959, 2008

